EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	59	715/705,707-709.cds. and (correct\$3 repair\$3 recover\$3) near3 (instruct\$3 display\$3 show\$3 depict\$3)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	ON	2008/11/18 10:13
L4	41	715/705,707-709.cds. and ("power supply" UPS) with (repair\$3 correct\$3 recover\$3 diagnos\$3)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	ON	2008/11/18 10:15
L5	13	715/710.cols. and (("power supply" UPS) with (repair\$3 correct\$3 recover\$3 diagnos\$3) (correct\$3 repair\$3 recover\$3) near3 (instruct\$3 display\$3 show\$3 depict\$3))	US-PCPUB; USPAT; EPO; JPO; IBM_TDB	OR	ON	2008/11/18 10:17
L7	201	714/1-57.ccls. and (display\$3 show\$3 depict \$3) near3 (procedure instruction step) and (correct\$3 repair\$3 recover\$3) near3 (instruct\$3 display\$3 show\$3 depict\$3) same (user technician operator engineer repairman)	US-PCPUB; USPAT; EPO; JPO; IBM_TDB	OR	ON	2008/11/18 11:55
L8	374	(714/22).OCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/11/18 11:55
L9	8	714/14,24.ccls. and ("uninterruptible power supply" "ups") near2 (connect\$4 install\$5 operat\$4) with (check\$3 monitor\$3 determin\$3) same (alert\$3 error fault fail\$3)	US-PCPUB; USPAT; EPO; JPO; IBM_TDB	OR	ON	2008/11/18 11:56
L10	34	714/14,24.ccls. and ("uninterruptible power supply" ups) same status same (alert monitor\$3 error warn\$3)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	ON	2008/11/18 11:56

L11	6	715/961,965,966.cds. and (display\$3 show\$3 depict\$3) near3 (procedure instruction step) and (correct\$3 repair\$5 recover\$3 display \$3 show\$3 depict\$3) same (user technician operator engineer repairman)	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	ON	2008/11/18 12:54
L12	30	715/961,965,966.cds. and (("power supply" UPS) with (repair\$3 correct\$3 recover\$3 diagnos\$3) (correct\$3 repair\$3 recover\$3) near3 (instruct\$3 display \$3 show\$3 depict\$3))	US-PGPUB; USPAT; EPO; JPO; IBM_TDB	OR	ON	2008/11/18 13:10
L13	1	("20010011845").PN.	US-PGPUB; USPAT; USOOR	OR	OFF	2008/11/18 14:41
L17	56	(("power supply" ups) and (sensor monitor sensing monitoring) and (display\$3 show\$3) near3 (correct\$3 recover \$3 repair\$3 fix\$3) and (step instruction)).clm.	US-PGPUB	OR	ON	2008/11/18 15:18

11/18/2008 3:52:35 PM

C:\ Documents and Settings\ jschell\ My Documents\ EAST\ Workspaces\ APP10.622952.wsp